## International Progress Report

IPR-02-35

# Äspö Hard Rock Laboratory

**Canister Retrieval Test** 

Sensors data report (Period: 001026-020501)

Report no: 4

Reza Goudarzi Lennart Börgesson Clay Technology AB

Kennert Röshoff Nancy Bono BBK

May 2002

#### Svensk Kärnbränslehantering AB

Swedish Nuclear Fuel and Waste Management Co Box 5864 SE-102 40 Stockholm Sweden

Tel +46 8 459 84 00 Fax +46 8 661 57 19



 $\begin{array}{ccc} \text{Report no.} & & \text{No.} \\ \text{IPR-02-35} & & \text{F69K} \\ \text{Author} & & \text{Date} \end{array}$ 

Goudarzi, Börgesson,

Röshoff, Bono 02-05-01 Checked by Date

Approved Date

Christer Svemar 02-10-23

# Äspö Hard Rock Laboratory

#### **Canister Retrieval Test**

Sensors data report

(Period: 001026-020501)

Report no: 4

Reza Goudarzi Lennart Börgesson

Clay Technology AB

Kennert Röshoff Nancy Bono

BBK

May 2002

*Keywords:* Buffer, bentonite, rock, temperature, stress, strain, test, measurements, swelling, full scale, in situ

This report concerns a study which was conducted for SKB. The conclusions and viewpoints presented in the report are those of the author(s) and do not necessarily coincide with those of the client.

## **Abstract**

This report presents data from the measurements in the Canister Retrieval Test from 001026 to 020501.

The following measurements are made in the bentonite: Temperature is measured in 32 points, total pressure in 27 points, pore water pressure in 14 points and relative humidity in 55 points. Temperature is also measured by all relative humidity gauges. The positions of the measuring points in the bentonite are related to a coordinate system in the deposition hole.

The following measurements are made in the rock: Temperature is measured in 40 points, stresses are measured in 8 points and strain is measured in 9 points. Stresses and strains are also measured in the rock around the empty deposition hole located 6 m south of the test hole.

The following measurements are made in the canister: Temperature is measured every meter along two fiber optic cables and strain is measured in 76 points on the surface of the copper envelop. Temperature is measured in the steel insert in 18 points.

The following measurements are made on the plug: Force is measured in 3 of the 9 anchors and vertical displacement is measured in three points.

The water inflow to the filter mats on the rock surface is also measured.

The general conclusion is that the measuring systems and transducers seem to work well but the following problems have been noted: The strain measurements in the canister are not reported due to question marks regarding the relevance of the results. Some Vaisala relative humidity transducers, most of them located in ring 5, have failed due to water saturation. Four Kulite total pressure transducers out of six seem to yield erroneous results.

In beginning of this latest half-year period two of the 36 electrical heaters failed due to short circuit to earth and no power was generated during one day between November 5 and 6 2001 (day 375). The heaters were also shut off during one week between March 4 and 11 2002 (days 495 to 502) for control measurements.

## Sammanfattning

I denna rapport presenteras data från mätningar i Återtag under perioden 001026-020501.

Följande mätningar görs i bentoniten: Temperaturen mäts i 32 punkter, totaltryck i 27 punkter, porvattentryck i 14 punkter och relativa fuktigheten i 55 punkter. Temperaturen mäts även i alla relativa fuktighetsmätare. Varje mätpunkt relateras till ett koordinatsystem i deponeringshålet.

Följande mätningar görs i berget: Temperaturen mäts i 40 punkter, bergspänningar mäts i 8 punkter och töjningar i 9 punkter. Bergspänningar och töjningar mäts också i berget runt det tomma deponerinshålet 6 m söder om försökshålet.

Följande mätningar görs på ytan i kapselns kopparhölje: Temperaturen mäts varje meter längs två fiberoptiska kablar och töjning mäts i 76 punkter. Temperaturen mäts i stålinsatsen i kanistern i 18 punkter.

Följande mätningar görs på pluggen: Kraften mäts i 3 av de 9 stagen och vertikala förskjutningen mäts i tre punkter.

Vatteninflödet till filtermattorna mäts också.

En generell slutsats är att mätsystemen och givarna tycks fungera bra, men följande problem har noterats: Töjningsmätningarna i kapseln har inte redovisats p. g. a frågetecken beträffande mätresultatens relevans. Några av Visalas relativa fuktighetsmätare, de flesta belägna i ring 10, har slutat fungera p. g. a. vattenmättnad. Fyra Kulite totaltrycksgivare av totalt sex tycks ge felaktiga resultat.

I början av den senaste halvårsperioden slutade två av 36 av electriska värmarna i kapsel att fungera p.g.a. kortslutning till jord och ingen värme genererades mellan 5 och 6 november 2001 (dag 375). Alla värmarna stängdes också av under en vecka 4-11 mars 2002 (fr.o.m. dag 495 till 502) för kontrollmätningar.

## **Contents**

1	Introduction	9
2	Comments	11
2.1	General	11
2.2	Total pressure, Geocon (App. A pages 33-36)	11
2.3	Total Pressure, Kulite (App. A page 37)	12
2.4	Suction, Wescore Psychrometers (App. A pages 38-44)	12
2.5	Relative humidity, Vaisala (App. A pages 45-49)	12
2.6	Pore water pressure, Geocon (App. A pages 50-51)	12
2.7	Pore water pressure, Kulite (App. A page 52)	13
2.8	Water flow into the filters (App. A page 53)	13
2.9	Forces on the plug (App. A page 54)	13
2.10	Displacement of the plug (App. A page 55)	13
2.11	Canister power (App A . page 56)	13
2.12	Temperature in the buffer (App. A pages 57-61)	13
2.13	Temperature in the rock (App. A pages 62-65)	14
2.14	Temperature on the canister surface, Optical fiber cables	
	(App. A pages 66-67)	14
2.15	Temperature inside the canister (App. A pages 68-69)	14
2.16	Strain in the canister	14
2.17	Rock stresses and strains	14
3	Geometry	15
4	Location of instruments	17
4.1	Brief description of the instruments	17
4.2	Strategy for describing the position of each device	19
4.3	Position of each instrument in the bentonite	19
4.4	Instruments in the rock	24
4.5	Instruments in the canister	25
4.6	Instruments at the plug	28
	References	29
	Appendix A (measured data)	31

## 1 Introduction

The installation of the Canister Retieval Test was made during autumn 2000. In general the data in this report are presented in diagrams covering the time period 2000-10-26 to 2002-05-01. The time axis in the diagrams represents days from 2000-10-26. The diagrams are attached in Appendix 1. The stress and strain measurements in the rock are reported separately by BBK. That report is attached as Appendix 2.

A test overview with the positions of the measuring points and a brief description of the instruments is also presented in this report (chapters 3 and 4).

General comments concerning the collected data are given in chapter 2.

## 2 Comments

#### 2.1 General

In this chapter short comments on general trends in the measurements are given. Sensors that are not delivering reliable data or no data at all are noted and comments on the data in general are given.

The slot between rock and bentonite block was filled with bentonite pellets and water at 001026. This date is also marked as start date. 1 m water head in the water supply tank was connected to the filters on 001102.

The heating of the canister started with an initially applied constant power of 700 W at 001027 that is one day after test start. The power was raised to 1700 W on 001113. The power was further raised to 2600 W on 010213.

In beginning of this latest half-year period two of the 36 electrical heaters failed due to short circuit to earth and no power was generated during one day between November 5 and 6 2001 (day 375). The heaters were also shut off during one week between March 4 and 11 2002 (days 495 to 502) for control measurements.

The third report covered the period up to 011101. This report is the fourth one and covers the results up to 020501.

## 2.2 Total pressure, Geocon (App. A pages 33-36)

The two periods of power shut off with decreased temperature are clearly reflected by the pressure measurements with decreasing pressure and a rather fast recovery.

The measured pressure range is from 0 to 5.7 MPa. The highest pressure is indicated from P105, P107, P109 and P114. The three first ones are placed in Cylinder 1 and all of them are placed at the same distance from the canister and near the bentonite block periphery. P114 is placed in Ring5 in the slot at the bentonite block periphery. P112 and U106, placed near the bentonite block periphery in ring 5, have increased to 2.4 – 2.8 MPa. Remarkable is that P110, P115 and P113 placed close to the canister has increased to 2.7- 3.6 MPa while P116, placed close to the rock surface, has only increased to about 0.50 MPa. P111 placed half way between the rock and the canister in ring 5 has increased to 2.6 MPa under this period.

If each section is considered separately all Geocon total pressure sensors show logical increase in pressure with increased radial distance from the canister surface except for section C in ring 5, where P116 close to the rock yields 0.5 MPa and P115 close to the canister yields 3.1 MPa.

Sensor P104 was not installed. U106 was originally intended to be a pore pressure sensor but was replaced by a total pressure sensor.

## 2.3 Total Pressure, Kulite (App. A page 37)

Six Kulite total pressure transducers are installed in the bentonite blocks. Three of them yielded questionable data rather early in the test: P22 stopped working properly after 125 days. The only transducers that seem to function properly are the two transducers placed above the center of the canister, which yield logically very low pressure. The reason for the malfunction seems to be brakeage of the transducer connections at high pressures.

## 2.4 Suction, Wescore Psychrometers (App. A pages 38-44)

Wescor psychrometers are only working at suction below 5000 kPa, which correspond to high relative humidity (above about 96%). Twelve transducer W141, W147, W124, W130, W140, W146, W149, W122, W123, W128, W129 and W109 started yielding values that could be interpreted in the three earlier reports. During the latest sex months another transducer (W145) have started yielding interpretable values. This transducer is placed in Ring10 near the canister. In Ring 5 six out of eight transducers are indicating a high relative humidity and after about 250 days the water seems to have reached through the entire buffer in two directions. In ring 10 all eight transducers indicate a high relative humidity.

## 2.5 Relative humidity, Vaisala (App. A pages 45-49)

App. pages 36-40 show relative humidity and temperature measured with Vaisala transducers. The relative humidity results and the temperature results in ring 10 have been split into two diagrams (pages 38 and 39) since the data were interfering with each other.

W112 was not installed. W102 and W125 were out of order from start and they are not plotted in this report. W103, W150, W138, W136, W137 W119, W120, W127, W101, W118 and W143 and W144 stopped working during the first year. During the last six months another transducers has stopped working (W121). This transducer is placed near the bentonite block periphery in ring 5.

The reason for the successive malfunction of these is not clear but the transducers do not work very well at high relative humidity. It is interesting to note that the drying indicated by transducers W134 and W135, which are placed just above the canister, has stopped and seems to turn into a slow wetting. All transducers between the rock and the canister in rings 5 and 10 indicate a high degree of saturation, which confirm the results of the Wescor psychrometers.

## 2.6 Pore water pressure, Geocon (App. A pages 50-51)

U105, U105, U108 and U110 yield a water pressure of between 150 and 300 kPa. They are placed in Ring 5. The pressure measured by these transducers is most likely a pore gas pressure since the water pressure applied in the filters in the periphery is only 55 kPa at that level. The remaining sensors of this type yield pressure close to zero.

U106 is replaced by a total pressure sensor.

## 2.7 Pore water pressure, Kulite (App. A page 52)

There are only one sensor of this type in Ring 10 and one in Cylinder 4. Both indicate pressure close to zero.

## 2.8 Water flow into the filters (App. A page 53)

Measurement of water inflow into the filters started on 001102. The total inflow to the filter has since that date been 256 liter. The inflow is slowly reduced with time and at present about 0.015 l/day.

## 2.9 Forces on the plug (App. A page 54)

The forces on the plug have been measured since 001106. The total force is about 4800 kN at 020501.

During the first about 50 days the plug was only fixed with 3 rods. When the total force exceeded 1500 kN the rest of the 9 rods were fixed in a prescribed manner. This procedure took place 12-14 December 2000 that is 46-48 days after test start. From that time only every third anchor is measured and the results should thus be multiplied with 3. The diagram shows both the actual measurements and after multiplication with 3.

## 2.10 Displacement of the plug (App. A page 55)

The three displacement gauges were placed and started to measure displacements from 001101. The tilting of the plug that could be observed in the beginning of the test has ceased and the displacement after 100 days seems to be the same in all three points except for the last month, when transducer 1 has settled. The reason for this change in behavior is not known..

## 2.11 Canister power (App A . page 56)

A constant power of 2600 W is applied and measured. The failure at day 375 and the turn off at days 495 to 502 are noted as intermissions in the curve.

## 2.12 Temperature in the buffer (App. A pages 57-61)

The measured drop in temperature at the power turn off was at most about 22 degrees (6 cm from the canister in ring 5), where also the highest temperature 86 °C is read. The highest temperature gradient is about 0.90 degrees/cm (ring 5).

### 2.13 Temperature in the rock (App. A pages 62-65)

The maximum temperature measured in the rock (63 degrees) is measured in the central section on the surface of the deposition hole. Almost complete axial symmetry of the temperature measured in the rock is observed.

One thermocouple (TR139) has stopped working during this period.

# 2.14 Temperature on the canister surface, Optical fiber cables (App. A pages 66-67)

The first diagram shows the maximum temperature plotted as a function of time. The maximum temperature measured on the canister surface is between 95 and 100 °C. The second diagram shows the distribution of the temperature along the cables at 020420. The length of the cable on the canister surface is only about 20 m and close to the entrances the lower surrounding temperatures affect the measured temperature.

Problems with the data collection system have yielded loss of measurements at long intervals.

#### 2.15 Temperature inside the canister (App. A pages 68-69)

The drop in temperature at the one week power turn off is strong and reduces the temperature of the canister to 50 °C. The temperature is almost completely recovered. The difference in measured temperature has increased after the power brake down.

#### 2.16 Strain in the canister

Continuous measurements have been made but so far no results have been produced due to evaluation problems.

#### 2.17 Rock stresses and strains

Rock stresses and strains are reported in Appendix B.

## 3 Geometry

The test installation consists of a full-scale deposition hole, a copper canister equipped with electrical heaters and bentonite blocks (cylindrical and ring shaped). A plug of concrete and steel is anchored to the rock on top of the bentonite.

The saturation of the bentonite is attained artificially by vertical filter stripes. 16 stripes with a width of 0.1 meters and a length of 5.5 meters are applied on the surrounding rock.

Measurements are made in four vertical sections A, B, C and D according to Figure 3-1. Direction A-B is parallel to the tunnels axial with A headed almost against north.




Figure 3-1. Figure describing the instrument planes (A-D) and the coordinate system used when describing the instrument positions.

## 4 Location of instruments

## 4.1 Brief description of the instruments

The different instruments that are used in the experiment are briefly described in this chapter.

#### Measurements of temperature

#### Buffer

Thermocouples from BICC have been installed for measuring temperature in the buffer. Measurements are done in 32 points in the test hole. In addition, temperature gauges are built in into the capacitive relative humidity sensors (29 sensors) as well as in the pressure gauges of vibrating wire type (13 gauges). Temperature is also measured in the psychrometers.

#### Canister

Temperature is measured inside the canister (on the insert) in 19 points with PT-100 gauges. In addition temperature is measured on the surface of the canister with optical fiber cables. An optical measuring system called FTR (Fiber Temperature Laser Radar) from BICC is used.

#### Rock

Temperature in the rock and on the rock surface of the hole is measured in 40 points with thermocouples from BICC.

#### Measurement of total pressure in the buffer

Total pressure is the sum of the swelling pressure and the pore water pressure. It is measured with the following instrument types:

- Geocon total pressure cells with vibrating wire transducers. 15 cells of this type have been installed.
- Kulite total pressure cells with piezo resistive transducers. 6 cells of this type have been installed.

#### Measurement of pore water pressure in the buffer

Pore water pressure is measured with the following instrument types:

- Geocon pore pressure cells with vibrating wire transducer. 13 cells of this type have been installed.
- Kulite pore pressure cells with piezo resistive transducer. 2 cells of this type have been installed.

#### Measurement of the water saturation process

The water saturation process is recorded by measuring the relative humidity in the pore system, which can be converted into water ratio or total suction (negative water pressure). The following techniques and devices are used:

- Vaisala relative humidity sensor of capacitive type. 29 cells of this type have been installed. The measuring range is 0-100 % RH.
- Wescor psychrometers model PST-55. The devices measure the relative humidity in the pore system. The measuring range is 95.5-99.6 % RH corresponding to the pore water pressure -0.5 to -6MPa. 26 cells of this type have been installed.

#### **Measurements of strain in the Canister**

These measurements are not reported.

#### Measurements of stresses and strain in the rock

These measurements are not reported.

#### Measurements of forces on the plug

The force on the plug caused by the swelling pressure of the bentonite is measured in 3 of the 9 anchors. The force transducers are of the type GLÖTZL.

#### Measurements of plug displacement

Due to straining of the anchors the swelling pressure of the bentonite will cause not only a force on the plug but also displacement of the plug. The displacement is measured in three points with transducers of the type LVDT with the range 0-50 mm.

#### Measurement of water flow into the permeable mats

Water is supplied to the bentonite with filter strips attached to the rock surface. The water flow into these mats is measured by measuring the water volume in the supply tank with a differential pressure transmitter that measures the difference in pressure between the nitrogen in the top of the tank and the water in the bottom of the tank.

## 4.2 Strategy for describing the position of each device

Every instrument is named with a short unique name consisting of 1-2 letters describing the type of measurement and 3 figures numbering the device. Every instrument position in the buffer and rock is described with three coordinates according to Figure 3-1.

The r-coordinate is the horizontal distance from the center of the hole and the z-coordinate is the height from the bottom of the hole (the block height is set to 500 mm). The  $\alpha$ -coordinate is the angle from the vertical direction B (almost south).

The short description of the positions in the diagrams differs between the buffer and the rock.

**Buffer:** Three positions with the following meaning: (bentonite block or cylinder number counted from the bottom  $\setminus$  direction A, B, C, or D  $\setminus$  radius in mm from center line)

**Rock:** Three positions with the following meaning: (distance in meters from the bottom  $\setminus \alpha$  according to Fig 3-1  $\setminus$  distance in meters from the hole surface)

The bentonite blocks are called cylinders and rings. The cylinders are numbered C1-C4 and the rings R1-R10 respectively (Figure 4-1).

#### 4.3 Position of each instrument in the bentonite

Measurements are done in four vertical sections A, B, C and D according to Figure 3-1. Direction A and B are placed in the tunnels axial direction.

An overview of the positions of the instruments is shown in Fig 4-1. Exact positions are described in Tables 4-1 to 4-4.

The instruments are located in two main levels in the blocks, 50 mm and 160 mm, from the upper surface. The thermocouples have mostly placed in the 50mm level and the other gauges in the 160 mm level.

o pore water pressure + temp.  $\Box$  total pressure + temp. × temp. 1m △ relative humidity (+ temp.) B+CA D 20 C4  $\Box$ C3 ゐ Д× C2 <u>₩</u>₩ R10 **R**9 R8 R7 R6 ×××× R5 R4 R3 R2 **R**1 ₽ ₹-5 

Figure 4-1 Schematic view over the instruments in four vertical sections and the block designation.

Table 4-1 Numbering and position of instruments for measuring temperature (T)

		Instrum	Instrument position in block					
Type and number	Block	Direction	α	r	Z	α	Fabricate	Remark
T101	Cyl. 1	Center	90	50	50	242	BICC	
T102	Cyl. 1	Center	90	50	250	238	BICC	
T103	Cyl. 1	Center	90	50	450	230	BICC	
T104	Cyl. 1	Α	180	635	450	206	BICC	
T105	Cyl. 1	Α	180	735	450	202	BICC	
T106	Cyl. 1	В	365	685	450	38	BICC	
T107	Cyl. 1	С	275	685	450	274	BICC	
T108	Cyl. 1	D	90	585	450	96	BICC	
T109	Cyl. 1	D	90	685	450	94	BICC	
T110	Cyl. 1	D	90	785	450	92	BICC	
T111	Ring 5	Α	180	635	2950	224	BICC	
T112	Ring 5	Α	180	735	2950	218	BICC	
T113	Ring 5	В	360	610	2950	318	BICC	
T114	Ring 5	В	360	685	2950	322	BICC	
T115	Ring 5	В	360	735	2950	324	BICC	
T116	Ring 5	С	270	610	2950	258	BICC	
T117	Ring 5	С	270	685	2950	260	BICC	
T118	Ring 5	С	270	735	2950	262	BICC	
T119	Ring 5	D	90	585	2950	44	BICC	
T120	Ring 5	D	90	635	2950	46	BICC	
T121	Ring 5	D	90	685	2950	48	BICC	
T122	Ring 5	D	90	735	2950	50	BICC	
T123	Ring 5	D	90	785	2950	52	BICC	
T124	Ring 10	Α	180	635	5450	200	BICC	
T125	Ring 10	Α	180	735	5450	194	BICC	
T126	Ring 10	D	90	585	5450	54	BICC	
T127	Ring 10	D	90	685	5450	56	BICC	
T128	Ring 10	D	90	785	5450	58	BICC	
T129	Cyl. 3	Α	180	785	6250	166	BICC	
T130	Cyl. 3	В	365	585	6250	358	BICC	
T131	Cyl. 3	С	275	585	6250	280	BICC	
T132	Cyl. 4	Α	180	785	6950	66	BICC	

Table 4-2 Numbering and position of instruments for measuring total pressure (P)

		Instrum	Instrument position in block			Cable pos.		
Type and number	Block	Direction	α	r	Z	α	Fabricate	Remark
P101	Cyl. 1	Center	180	50	50	244	Geocon	
P102	Cyl. 1	Center	180	50	250	232	Geocon	
P103	Cyl. 1	Α	185	585	250	208	Geocon	
P104	Cyl. 1	Α	185	685	250	204	Geocon	
P105	Cyl. 1	Α	185	785	250	186	Geocon	
P106	Cyl. 1	В	365	585	250	40	Geocon	
P107	Cyl. 1	В	365	785	250	2	Geocon	
P108	Cyl. 1	С	275	585	250	278	Geocon	
P109	Cyl. 1	С	275	785	250	270	Geocon	
P110	Ring 5	Α	185	585	2750	228	Geocon	
P111	Ring 5	Α	185	685	2750	222	Geocon	
P112	Ring 5	Α	185	785	2750	188	Geocon	
P113	Ring 5	В	365	535	2750	36	Geocon	
P114	Ring 5	В	365	825	2750	16	Geocon	
P115	Ring 5	С	275	585	2750	296	Geocon	
P116	Ring 5	С	275	785	2750	290	Geocon	
P117	Ring 10	Center	180	50	5250	24	Kulite	
P118	Ring 10	Α	180	585	5250	216	Geocon	
P119	Ring 10	Α	180	685	5250	198	Geocon	
P120	Ring 10	Α	180	785	5250	192	Geocon	
P121	Ring 10	В	365	585	5250	20	Kulite	
P122	Ring 10	В	365	785	5250	18	Kulite	
P123	Ring 10	С	275	585	5250	286	Kulite	
P124	Ring 10	С	275	785	5250	284	Kulite	
P125	Cyl. 3	Center	180	50	6250	158	Geocon	
P126	Cyl. 3	Α	180	585	6250	162	Geocon	
P127	Cyl. 4	Center	180	50	6750	64	Kulite	

Table 4-3 Numbering and position of instruments for measuring pore water pressure (U)

		Instrum	Instrument position in block			Cable pos.		
Type and number	Block	Direction	α	r	Z	α	Fabricate	Remark
U101	Cyl. 1	Center	270	50	50	246	Geocon	
U102	Cyl. 1	Center	270	50	250	236	Geocon	Horizontal
U103	Cyl. 1	Α	175	585	250	126	Geocon	
U104	Cyl. 1	Α	175	785	250	178	Geocon	
U105	Ring 5	Α	175	585	2750	138	Geocon	
U106	Ring 5	Α	175	785	2750	180	Geocon	
U107	Ring 5	В	355	535	2750	314	Geocon	
U108	Ring 5	В	355	825	2750	348	Geocon	
U109	Ring 5	С	265	585	2750	256	Geocon	In the slot
U110	Ring 5	С	265	825	2750	264	Geocon	In the slot
U111	Ring 10	Α	175	585	5250	146	Geocon	
U112	Ring 10	Α	175	785	5250	152	Geocon	
U113	Cyl. 3	Center	270	50	6250	156	Geocon	
U114	Cyl. 4	Center	270	50	6950	62	Kulite	

Table 4-4 Numbering and position of instruments for measuring water content (W)

Type and number         Block           W101         Cyl. 1           W102         Cyl. 1           W103         Cyl. 1           W104         Cyl. 1           W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5 <t< th=""><th>Direction Center</th><th>α</th><th>r</th><th>Z</th><th>α</th><th>]</th><th></th></t<>	Direction Center	α	r	Z	α	]	
W101         Cyl. 1           W102         Cyl. 1           W103         Cyl. 1           W104         Cyl. 1           W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132 <td>Center</td> <td></td> <td></td> <td></td> <td>ı u</td> <td>Fabricate</td> <td>Remark</td>	Center				ı u	Fabricate	Remark
W102         Cyl. 1           W103         Cyl. 1           W104         Cyl. 1           W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133 <td></td> <td>360</td> <td>50</td> <td>50</td> <td>248</td> <td>Vaisala</td> <td></td>		360	50	50	248	Vaisala	
W103         Cyl. 1           W104         Cyl. 1           W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134 <td>Center</td> <td>360</td> <td>400</td> <td>160</td> <td>240</td> <td>Vaisala</td> <td></td>	Center	360	400	160	240	Vaisala	
W104         Cyl. 1           W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135 <td>Center</td> <td>360</td> <td>50</td> <td>450</td> <td>234</td> <td>Vaisala</td> <td>Horizontal</td>	Center	360	50	450	234	Vaisala	Horizontal
W105         Cyl. 1           W106         Cyl. 1           W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136 </td <td>Α</td> <td>180</td> <td>585</td> <td>340</td> <td>128</td> <td>Vaisala</td> <td></td>	Α	180	585	340	128	Vaisala	
W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W140	Α	180	685	340	132	Vaisala	
W107         Cyl. 1           W108         Cyl. 1           W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138	Α	180	785	340	184	Vaisala	
W109         Cyl. 1           W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W1	Α	170	585	340	124	Wescor	
W110         Cyl. 1           W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W	Α	170	685	340	130	Wescor	
W111         Cyl. 1           W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10	Α	170	785	340	134	Wescor	
W112         Cyl. 1           W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10 <t< td=""><td>В</td><td>360</td><td>585</td><td>340</td><td>304</td><td>Vaisala</td><td></td></t<>	В	360	585	340	304	Vaisala	
W113         Cyl. 1           W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	360	785	340	360	Vaisala	
W114         Cyl. 1           W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	360	685	340	308	Vaisala	
W115         Cyl. 1           W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	355	585	340	302	Wescor	
W116         Cyl. 1           W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	355	685	340	306	Wescor	
W117         Cyl. 1           W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	355	785	340	310	Wescor	
W118         Cyl. 1           W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	С	270	585	340	250	Wescor	
W119         Ring 5           W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	С	270	685	340	252	Wescor	
W120         Ring 5           W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	С	270	785	340	254	Vaisala	
W121         Ring 5           W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	180	585	2840	226	Vaisala	
W122         Ring 5           W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	180	685	2840	220	Vaisala	
W123         Ring 5           W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	180	785	2840	182	Vaisala	
W124         Ring 5           W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	170	585	2840	136	Wescor	
W125         Ring 5           W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	170	685	2840	140	Wescor	
W126         Ring 5           W127         Ring 5           W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	Α	170	785	2840	142	Wescor	
W127       Ring 5         W128       Ring 5         W129       Ring 5         W130       Ring 5         W131       Ring 5         W132       Ring 5         W133       Ring 5         W134       Ring 10         W135       Ring 10         W136       Ring 10         W137       Ring 10         W138       Ring 10         W139       Ring 10         W140       Ring 10         W141       Ring 10         W142       Ring 10         W143       Ring 10         W144       Ring 10         W145       Ring 10	В	360	535	2840	316	Vaisala	In the slot
W128         Ring 5           W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	360	685	2840	34	Vaisala	
W129         Ring 5           W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	360	785	2840	350	Vaisala	
W130         Ring 5           W131         Ring 5           W132         Ring 5           W133         Ring 5           W134         Ring 10           W135         Ring 10           W136         Ring 10           W137         Ring 10           W138         Ring 10           W139         Ring 10           W140         Ring 10           W141         Ring 10           W142         Ring 10           W143         Ring 10           W144         Ring 10           W145         Ring 10	В	350	535	2840	312	Wescor	In the slot
W131       Ring 5         W132       Ring 5         W133       Ring 5         W134       Ring 10         W135       Ring 10         W136       Ring 10         W137       Ring 10         W138       Ring 10         W139       Ring 10         W140       Ring 10         W141       Ring 10         W142       Ring 10         W143       Ring 10         W144       Ring 10         W145       Ring 10	В	350	685	2840	320	Wescor	
W132       Ring 5         W133       Ring 5         W134       Ring 10         W135       Ring 10         W136       Ring 10         W137       Ring 10         W138       Ring 10         W139       Ring 10         W140       Ring 10         W141       Ring 10         W142       Ring 10         W143       Ring 10         W144       Ring 10         W145       Ring 10	В	350	785	2840	346	Wescor	
W133       Ring 5         W134       Ring 10         W135       Ring 10         W136       Ring 10         W137       Ring 10         W138       Ring 10         W139       Ring 10         W140       Ring 10         W141       Ring 10         W142       Ring 10         W143       Ring 10         W144       Ring 10         W145       Ring 10	С	270	585	2840	294	Wescor	In the slot
W134       Ring 10         W135       Ring 10         W136       Ring 10         W137       Ring 10         W138       Ring 10         W139       Ring 10         W140       Ring 10         W141       Ring 10         W142       Ring 10         W143       Ring 10         W144       Ring 10         W145       Ring 10	С	275	685	2840	292	Wescor	
W135 Ring 10 W136 Ring 10 W137 Ring 10 W138 Ring 10 W139 Ring 10 W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W144 Ring 10 W145 Ring 10 W145 Ring 10	С	270	785	2840	288	Wescor	
W136 Ring 10 W137 Ring 10 W138 Ring 10 W139 Ring 10 W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W144 Ring 10 W145 Ring 10	Center	360	50	5340	22	Vaisala	
W137 Ring 10 W138 Ring 10 W139 Ring 10 W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W144 Ring 10 W145 Ring 10	Α	180	262	5340	26	Vaisala	
W138 Ring 10 W139 Ring 10 W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W145 Ring 10 W145 Ring 10	Α	180	585	5340	214	Vaisala	
W139 Ring 10 W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W145 Ring 10	Α	180	685	5340	196	Vaisala	
W140 Ring 10 W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W145 Ring 10	A	180	785	5340	190	Vaisala	
W141 Ring 10 W142 Ring 10 W143 Ring 10 W144 Ring 10 W145 Ring 10	A	170	585	5340	144	Wescor	
W142 Ring 10 W143 Ring 10 W144 Ring 10 W145 Ring 10	A	170	685	5340	148	Wescor	
W143 Ring 10 W144 Ring 10 W145 Ring 10	A	170	785 595	5340	150	Wescor	
W144 Ring 10 W145 Ring 10	В	360	585	5340	328	Vaisala	
W145 Ring 10	В	360	685	5340	332	Vaisala	
	В	360	785 585	5340	336	Vaisala	
VV 140   King 10	В	355	585	5340	326	Wescor	
W147 Ring 10	B B	355	685 785	5340 5340	330 334	Wescor Wescor	
W147 Ring 10 W148 Ring 10	С	355 270	785 585	5340	266	Wescor	
	C						
	C	270	685 785	5340	268 272	Wescor	
W150 Ring 10 W151 Cyl. 3	Center	270 360	785 50	5340 6250	154	Vaisala Vaisala	
W152 Cyl. 3 W153 Cyl. 3	A B	180 360	585 585	6250 6250	160 356	Vaisala Vaisala	
,	С					Wescor	
W154 Cyl. 3 W155 Cyl. 4	Center	270 360	585 50	6250 6840	276 60	Vaisala	

#### 4.4 Instruments in the rock

#### **Temperature measurements**

40 thermocouples are placed in the rock and on the rock surface of the deposition hole. Holes have been bored in three directions on three levels and one additional hole has been bored in the bottom of the deposition hole i.e. totally 10 holes. They are led from the rock, over the gap between rock and bentonite and up along the bentonite block periphery. The position of the thermocouples in the rock is shown in Table 4-5.

Table 4-5 Numbering and positions of thermocouples in the rock

				Cable pos.		
Type and number	Level	Direction	Distance from rock surface	α	Fabricate	Remark
TR101	0	Center			BICC	
TR102	0	Center	0.375	70°-90° BICC		
TR103	0	Center	0.750	70°-90° BICC		
TR104	0	Center	1.500	70°-90°	BICC	
TR105	0.61	10°			BICC	
TR106	0.61	10°	0.375	4°-14°	BICC	
TR107	0.61	10°			BICC	
TR108	0.61	10°	1.500	4°-14°	BICC	
TR109	0.61	80°	0.000	70°-90°	BICC	
TR110	0.61	80°	0.375	70°-90°	BICC	
TR111	0.61	80°	0.750	70°-90°	BICC	
TR112	0.61	80°	1.500	70°-90°	BICC	
TR113	0.61	170°	0.000	168°-176°	BICC	
TR114	0.61	170°	0.375	168°-176°	BICC	
TR115	0.61	170°	0.750	168°-176°	BICC	
TR116	0.61	170°	1.500	168°-176°	BICC	
TR117	3.01	10°	0.000	4°-14°	BICC	
TR118	3.01	10°	0.375	4°-14°	BICC	
TR119	3.01	10°	0.750	4°-14°	BICC	
TR120	3.01	10°	1.500	4°-14°	BICC	
TR121	3.01	80°	0.000	70°-90°	BICC	
TR122	3.01	80°	0.375	70°-90°	BICC	
TR123	3.01	80°	0.750	70°-90°	BICC	
TR124	3.01	80°	1.500	70°-90°	BICC	
TR125	3.01	170°	0.000	168°-176°	BICC	
TR126	3.01	170°	0.375	168°-176°	BICC	
TR127	3.01	170°	0.750	168°-176°	BICC	
TR128	3.01	170°	1.500	168°-176°	BICC	
TR129	5.41	10°	0.000	4°-14°	BICC	
TR130	5.41	10°	0.375	4°-14°	BICC	
TR131	5.41	10°	0.750	4°-14°	BICC	
TR132	5.41	10°	1.500	4°-14°	BICC	
TR133	5.41	80°	0.000	70°-90°	BICC	
TR134	5.41	80°	0.375	70°-90°	BICC	
TR135	5.41	80°	0.750	70°-90°	BICC	
TR136	5.41	80°	1.500	70°-90°	BICC	
TR137	5.41	170°	0.000	168°-176°	BICC	
TR138	5.41	170°	0.375	168°-176°	BICC	
TR139	5.41	170°	0.750	168°-176°	BICC	
TR140	5.41	170°	1.500	168°-176°	BICC	

#### Stress and strain measurements

See Appendix B.

#### 4.5 Instruments in the canister

The canister is instrumented with optical fiber cables on the copper surface, thermocouples in the steel insert and strain gauges on the inner and outer surface of the copper envelop in canister.

#### **Optical fiber cables**

Figure 4-2 shows how the two optical fiber cables are placed on the canister surface. Both ends of a cable are used for measurements. This means that the two cables are used as four measuring channels as described in Table 4-6.

With this laying the cable will enter and exit the surface at almost the same position. Curvatures are shaped as a quarter circle with a radius of 20 cm. The cable is placed in a milled out channel on the surface. The channel has a width and a depth of just above 2 mm


Table 4-6. Combination of cables and channels

Channel 1	Outlet of cable 1
Channel 2	Inlet of cable 1
Channel 3	Outlet of cable 2
Channel 4	Inlet of cable 2


Figure 4-3 shows the location of the thermocouples on the steel insert inside the canister.

#### Thermocouple, PT100

Temperature in the steel insert measured at 18 point of measuring with. thermocouple of type PT100. Figure 4-4 shows how these thermocouple are placed



*Figure 4-2.* Laying of two optical fibre cables with protection tube of Inconel 625 (outer diameter 2 mm) for measurement of the canister surface temperature (surface unfolded).



Figur 4-3. Location of thermocouples inside the canister

## 4.6 Instruments at the plug

Three force transducers and three displacement transducers have been placed on the plug to measure the force of the anchors and the displacement of the plug. The location of these transducers can be described in relation to Fig 4-4, which shows a schematic view of the plug with the slots, rods and cables.

The rods are numbered 1-9 anti-clockwise and number 1 is assumed to be the northern rod in direction A. The force transducers are placed on rods 3, 6, and 9. The displacement transducers are placed between the rods 5 cm from the rock surface of the hole and according to Table 4-6. They are fixed on the rock surface and measure thus the displacement relative the rock.




Figure 4-4. Schematic view of the deposition hole, showing the position of the slots, the rods and the cables from the canister.

Table 4-6. Location of displacement transducers


Transducer No.	Located between rods No.
1	4 and 5
2	7 and 8
3	1 and 2


## References


/1-1/ Sanden T, Börgesson L. Report on instrument positions and preparation of bentonite blocks for instruments and cables May 2000. SKB IPR-00-14


# Appendix A


Measured data



























































### Inflow into filter (001026-020501)




## Forces on plug (001026-020501)





### **Displacement of plug (001026-020501)**





#### Canister power (001026-010501)





























# Temperature on the canister surface (001026-020422) Optical fiber cables




## Temperature profile on the canister surface (020420) Optical fiber cables



## Temperature inside the canister (001026-020501) PT-100



Temperature inside the canister (001026-020501) PT-100



# Appendix B

# **BBK**

# STRESS AND STRAIN MEASUREMENT OF THE ROCK MASS RETRIEVAL TEST AT ÄSPÖ

Measuring period

2001-11-01 - 2002-04-30

Kennert Röshoff

Nancy Bono

2002-07-10

BergByggKonsult AB Ankdammsgatan 20 171 43, Solna, Sweden Tel. 08-7595050 Fax 08-7595065

Con	itents	Page
1	EXTENT	77
2	TECHNICAL BACKGROUND	79
2.1	The vibrating wire embedment biaxial stressmeter	79
2.2	Embedded strain meters	79
2.3	Cement 79	
3	FIELD MEASUREMENT	81
3.1	Installation work	81
3.2	Location of instruments	81
3.3	Registration	81
4	COMPUTER PROCESSING OF FIELD DATA	85
4.1	Evaluation of stresses	85
4.1.1	Radial deformations	85
4.1.2	Calculation of deformation to stresses	85
4.1.3	Vertical stress change	86
4.2	Evaluation of strain	86
4.2.1	Calculation of strain	87
	Material parameters	87
4.4	Processing	87
5	RESULTS	89
5.1	Results of canister hole 1	93
5.1.1	Stress change for each biaxial stressmeter	93
5.1.2	Strainmeter A1:1, B1:1, C1:1, D1:1, D1:2 (temperature compensated)	97
5.1.3	Strainmeter C1:2 (temperature compensated)	97
5.2	Results of canister hole 2	98
5.2.1	Stress change for each biaxial stressmeter	98
	Strainmeter B2:1, C2:1, C2:2 (temperature compensated)	102
	ndix 1	103
Appe	ndix 2	105

### 1 EXTENT

BBK AB and NCC Teknik have, on commission of SKB, ÄSPÖ hard rock laboratory, performed rock mechanical measurements in the Repository tunnel at Äspö. The measurement program comprises of registration of the stress and the strain response around the two canister holes during drilling and heating of the rock mass.

In the first phase, the response of the rock mass was monitored during the drilling of the two canister holes (QPTD F69-00-21). This second phase includes the response registered during a heating phase. Hole 2, shown in Figure 3.1 and Figure 3.2, has a heating source while Hole 1 is open and not heated. The heating experiment started on 2000-10-27 and will continue for about five years.

The aim of the instrumentation is to monitor the stress changes due to heating of the rock mass in a canister hole. The strain meter is used to monitor the relative changes of strain of the intact rock and across fractures.

The commission extends over field measurement and evaluation.

BBK AB is responsible for measuring equipment, the mobilization, field measurement, the computer processing. BBK AB and NCC Teknik are responsible for the interpretation and report of the measurements.

This report presents the measurement results in the period of the heating phase from 2001-11-01 to 2002-04-30.

## 2 TECHNICAL BACKGROUND

## 2.1 The vibrating wire embedment biaxial stressmeter

The biaxial stressmeter, Geokon model 4350, is designed to measure compressive stress changes in rock, salt, concrete or ice. Principal stress changes are measured in the plane perpendicular to the borehole axes. The stressmeter consists of a high-strength steel cylinder that is grouted into a 60 mm borehole. Stress changes in the host material cause the cylinder to deform. Specification for the biaxial stressmeter is according to Appendix 1.

The radial deformation of the cylinder is measured by means of three pairs of vibrating wire sensors spaced at 60° intervals. Changes of stress produce corresponding changes in the resonant frequency of the sensors. These changes of frequency can be related to stress changes using factory-supplied calibrations. Longitudinal strain sensors and temperature sensors are also included in the stressmeter.

### 2.2 Embedded strain meters

The vibrating wire strain gages are designed for direct embedment in concrete. The strainmeter is 15 cm long and commonly used for strain measurement in foundations, piles, bridges, dams, tunnel liners etc. Specification for the strainmeter is according to Appendix 2.

The strain is measured using the vibrating wire principle. A length of a steel wire is tensioned between two end blocks that are embedded directly in concrete. Deformation (i.e. strain changes) of the concrete mass will cause the two end blocks to move relative to one another, thus altering the tension in the steel wire. The tension is measured by excitation of the wire and measuring its resonant frequency of vibration using an electro magnetic coil.


### 2.3 Cement

Special expansive grout was used to insure that the gage is in complete contact with the surrounding rock. The instruments are grouted in special cement from Denmark named Densitop T2. This cement is chosen to have as similar properties as the rock as possible. The compression strength is 150 MPa. The coefficient of expansion is approximate 8.5 microstrain/C° that is similar to hard rock as granite and as 85 % of common concrete.

## 3 FIELD MEASUREMENT

### 3.1 Installation work

Installation of the stressmeter gage is accomplished by inserting the gage into a grout-filled borehole using a setting tool and self-aligning setting rod.



The stress cell is orientated so that the first vibrating wire is orientated tangentially to the canister hole. The second string is orientated  $60^{\circ}$  from tangential direction and the third string is orientated  $120^{\circ}$  from tangential direction.

The strainmeters were fixed to a 6 mm glasfiber rod and pushed into the grout after the stress cell was installed.

### 3.2 Location of instruments

See figure 3.1 and figure 3.2.

## 3.3 Registration

A datalogger type Campbell CR10X has captured the measurements, which have been recorded once every hour during the period 2000-10-01 to 2001-01-01, and once every six hours during the period 2001-01-03 to 2002-04-30.






Figure 3.1 Measurement Layout

# Canister Hole 1

# Canister Hole 2



# **SECTION A-A**



- ☐ Biaxial stressmeter
- Deformationmeter

Figure 3.2 Location of instruments

## 4 COMPUTER PROCESSING OF FIELD DATA

### 4.1 Evaluation of stresses

The stress changes are evaluated from the measured deformations registered by the vibrating wires.

### 4.1.1 Radial deformations

Radial deformation for each of the strings are calculated with the equation:

 $V_r = (R_1 - R_0)^*$  Gagefactor (inc. or mm)

 $V_r$  = Radial deformation for each of the strings

 $R_1$ = Deformation reading in digits (= frequency  $^2$  / 1000)

 $R_0$ = Deformation zero reading in digits (= frequency  $^2$  / 1000)

The body of the stressmeter is restrained so it is assumed that the body will not expand even if the temperature changes. Temperature correction is made for thermal expansion of the wire. The coefficient for thermal expansion of wire is 12.2 microstrain per degree C. Temperature correction is added in the equation for radial deformation according to:

$$Vr = (R_0 - R_1) * G * 25.4 + (0.0000122) * 25.4 * (((T_1 + T_2)/2) - ((T_{0_1} + T_{0_2})/2))$$

G = Gage factor

 $T_{01}$  = Temperature of thermal zero expansion for string 1

 $T_{02}$  = Temperature of thermal zero expansion for string 2

 $T_1$ ,  $T_2$  = Temperatures for string 1 and string 2

### 4.1.2 Calculation of deformation to stresses

The magnitude and the direction of the stress changes are determined from the measured radial deformation of the sensor in three directions.

The equations below give the magnitude and the direction of the maximum stress increase and reduction in a plane perpendicular to the borehole axes:

Maximal stress increase

$$p = \frac{1}{2} \left[ \frac{1}{3B} \left( \left( 2V_{r_1} - V_{r_2} - V_{r_3} \right)^2 + 3\left( V_{r_2} - V_{r_3} \right)^2 \right)^{\frac{1}{2}} + \frac{1}{3A} \left( V_{r_1} + V_{r_2} + V_{r_3} \right) \right]$$

 $V_r$  = Radial deformation for string 1

 $V_r =$ Radial deformation for string 2

 $V_{r_3}$  = Radial deformation for string 3

A , B =Coefficients depending on the sensor geometry and the material properties

### Maximal stress reduction

$$q = \left[ \frac{1}{3A} \left( V_{r_1} + V_{r_2} + V_{r_3} \right) - p \right]$$

### Longitudinal stress correction:

$$v\varepsilon_{lT}E = v*(R_0 - R_T)G + (T_T - T_0)C$$

 $\upsilon$  = Poisson's ratio of the rock

 $E_i = Youngs's Modulus of the rock$ 

 $\varepsilon_{lT} = longitudinal strain$ 

### The angle of the maximal stress increase

The angle in the plane perpendicular to the borehole axes is measured clockwise from the tangential direction of the canister hole.

$$\theta = \frac{1}{2} \cos^{-1} \left[ \frac{V_{r_1} - A(p+q)}{B(p-q)} \right]$$

### 4.1.3 Vertical stress change

The changes of stresses in vertical direction has been calculated and evaluated from the longitudinal deformation in the borehole direction. Two vibrating wires monitored the vertical stress change along the borehole.

Calculation of stresses according to position 4.1.2.

### 4.2 Evaluation of strain

Nine strain gages were installed in the same boreholes as the biaxial stressmeters.

### 4.2.1 Calculation of strain

Strain measurement were calculated as temperature compensated load related strain with the following equation:

$$\mu_{true} = (R_1 - R_0) * B + (T_1 - T_0)(C_1 - C_2)$$

 $\mu_{true}$  = temperature compensated microstrain

 $R_1$  and  $R_0$  =Digits reading

B =batch calibration factor

 $C_1$  and  $C_2$  are the coefficients of expansion of steel and concrete, 12.2 microstrian/ $C^{\circ}$  and 8.5 microstrain/ $C^{\circ}$ .

# 4.3 Material parameters

Material parameters used in the calculations are as the following:

- Young's modulus of intact rock 69 Gpa
- Poisson's ratio of intact rock 0.25
- Coefficients of expansion of steel 12.2 microstrain/ C°
- Coefficients of expansion of concrete 8.5 microstrain/C°

# 4.4 Processing

The raw data registered have been processed in Microsoft Excel software. The calculation and evaluation gathered from the deformations in the plane perpendicular to the borehole axes are presented as:

**Temperature** 

Radial deformation of the three pairs of wires in plane perpendicular to borehole axes

Maximal stress increases and stress reduction in plane perpendicular to borehole axes

Orientation of maximal stress increase in plane perpendicular to borehole axes

Vertical stress changes

Stress correction in plane due to vertical stress changes

Strain measurement

## 5 RESULTS

A summary of the results of the stress changes is presented in Table 1. These values represent total changes in stress magnitude and stress orientation during each reporting period during phase 2 (heating) together with maximum changes in stress magnitude and orientation recorded during phase 1 (drilling). Figure 5.1 presents graphically the maximum typical changes in stress magnitude and orientation during this reporting period from 2001-11-01 to 2002-04-30. These results are not compensated for temperature changes.

Although the measurements of stressmeters are affected by temperature, the temperature compensated results of stressmeters are not presented in this report because a further detailed study of the relationship between temperature and stressmeter measurements will be required in order to quantify these effects. Results of the biaxial stressmeter without temperature compensation and the strainmeter with temperature compensation from each borehole for the measuring period 2001-11-30 to 2002-04-30 are summarized on the diagrams in section 5.1 and 5.2.

The diagrams in section 5.1 and 5.2 for each borehole display:

- Maximum stress increases and stress reductions in plane perpendicular to borehole axes.
- Orientation of maximum stress increase in plane perpendicular to borehole axes.
- Strain measurements presented in the diagrams are temperature-compensated with the unit of microstrain. Positive values represent elongation.

The data during this reporting period indicate that:

• The temperature is inhomogeneous around these two canister holes.

### Hole 1

Around canister hole 1 (unheated) temperatures which had steadily risen several degrees during the previous six month period have now generally stabilised and are typically about 22°C to 23°C with the exception of B1. At stressmeter B1, which is nearest to canister hole 2, temperatures have increased to 26°C to 27°C.

It was also noted that temperatures around Hole 1 dropped 1 to 2°C degrees rather suddenly following 7 January 2002 and are now gradually increasing and approaching the values recorded prior to this decrease.

#### Hole 2

Around canister hole 2 (heated) the instruments located at greater depths (B2, C2 and B2:1) have maximum temperatures of about 56°C to 58°C. During the first half of March, temperatures at these instruments dropped by about 10 °C, and then began increasing toward these maximum values by the end of April.

Instruments located at higher levels in Hole 2 have maximum temperatures from 27°C to 30°C.

- In canister hole 1 the stress changes during this reporting period have been small (approximately 1MPa), and generally follow the gradual temperature change during the time period. The change in orientation of the stress field has also been very small and has reflected the temperature changes.
- In canister hole 2 the two stressmeters located at higher levels (A2 and D2) show small variations (about 1MPa) which follow the measured temperatures, and the orientation of the stress field has also shown a change that follows the temperature curve, with changes of about 2 to 3 degree.

The two stress meters located at lower levels in canister hole 2 have show larger stress changes during this reporting period. At B2 the stresses have increased to 57.9MPa, with a widening gap between the stresses measured in gages 1-3 and those measured in gages 4-6.

At stressmeter C2 the stresses have increased to 33.7MPa, also with a widening gap between the two sets of gages. In addition the orientation of the stress field measured at the two sets of gages have changed in different directions, although the maximum change in reading has been about 2 degrees, with a difference of about 3.5 degrees between the two readings

On two days during April the recorded data from one of the 8 vibrating wire gages within stressmeter C2 was –99999, which indicates that an error occurred while taking the reading.

Recorded changes in the strainmeters have been relatively small, with typical maximum change of about 10 to 20 microstrain, and the measured changes in gage lengths have reflected the changes in temperature with an increase in temperature resulting in shortening of the gage length. At gage B2:1 the gage reading temporarily changed by 91 microstrain with an 8 °C temperature change.




Figure 5.1 Maximum stress changes uncompensated for temperature

Stress-				Measuring	period				
meter	Phase	e 1: Drilling ph	nase	Phase 2: Heating phase					
				Period: 2000-10-01 – 2001-11-30 Period: 2001-11-01 – 2002-04-30				-04-30	
	Typical max. stress increase (MPa)	Typical max. stress reduction (MPa)	Orientation of max. stress increase (degree)	Typical max. stress increase (MPa)	Typical max. stress reduction (MPa)	Orientation of max. stress increase (degree)	Typical max. stress increase (MPa)	Typical max. stress reduction (MPa)	Orientation of max. stress increase (degree)
A1	17.0	-10.0	11.5	22.7	-10. 9	10.3	22.6	-10.8	10.3
B1	15.0	-11.0	17.0	21.1	-10. 3	16.8	26.9	-10. 5	16.8
C1	12.0	-7.4	0	21.9	-9.9	5.4	21.9	-9.8	5.4
D1	22.0	-11.0	0	25.8	-9.1	0	26.3	-9.4	0
A2	5.0	-4.0	-11.0	4.4	-3.3	-18.3	3.7	-3.3	-17.7
B2	11.0	-7.3	-7.5	31.1	-4.6	-14.1	57.9 (*)	-4.6	-21.3
C2	11.0	-7.7	29.5	29.1	-6.6	31.2	33.7 (*)	-7.6	30.2
D2	9.3	-7.2	38.5	16.5	-9.9	38.7	16.2	-9.9	38.3

### Notes:


- Positive values of stress indicate compression; Negative values of stress indicate extension.
- Positive values of orientation indicate anti-clockwise rotation; Negative values of orientation indicate clockwise rotation.
- Typical maximum stress increases and reductions represent maximum stabilised readings during the measuring period. (\*) indicates that the reading had not stabilised during the measuring period.
- Orientation of maximum stress increase is the orientation that corresponds to the typical maximum stress increase.

Table 1. Summary of results for stress measurements


### 5.1 Results of canister hole 1

# 5.1.1 Stress change for each biaxial stressmeter Biaxial stressmeter A1 uncompensated for temperature:

Maximum stress increase and reduction





### Orientation



### Biaxial stressmeter B1 uncompensated for temperature:


### Maximum stress increase and reduction






**Biaxial stressmeter C1 uncompensated for temperature:** 

### Maximum stress increase and reduction





### Orientation:




### Biaxial stressmeter D1 uncompensated for temperature:

### Maximum stress increase and reduction






5.1.2 Strainmeter A1:1, B1:1, C1:1, D1:1, D1:2 (temperature compensated)



Positive values of microstrain represent elongation

### 5.1.3 Strainmeter C1:2 (temperature compensated)




Positive values of microstrain represent elongation


### 5.2 Results of canister hole 2

### 5.2.1 Stress change for each biaxial stressmeter

### **Biaxial stressmeter A2 uncompensated for temperature:**


Maximum stress increase and reduction






### Biaxial stressmeter B2 uncompensated for temperature:


Maximum stress increase and reduction






### Biaxial stressmeter C2 uncompensated for temperature:


Maximum stress increase and reduction







### Biaxial stressmeter D2 uncompensated for temperature:

Maximum stress increase and reduction





## 5.2.2 Strainmeter B2:1, C2:1, C2:2 (temperature compensated)



Positive values of microstrain represent elongation

# **Appendix 1**

### Model 4350 VW Biaxial Stressmeter

The Model 4350 VW Biaxial Stressmeter is designed to measure compressive stress changes in rock, salt, concrete or ice. Three or six VW sensors oriented at 60° intervals allow the principal stress changes to be measured in the plane perpendicular to the stressmeter axis. The stressmeter consists of a high strength steel cylinder which is grouted (or frozen, in the case of ice) into a BX (60mm (2.36in.)) size borehole

### **Specifications**

Standard Range	70 MPa (10,000psi)
Sensitivity <sup>1</sup>	14 to 70 KPa (2 to 10psi)
Accuracy	±0.1% F.S.
Temperature Range <sup>2</sup>	-20°C to +80°C
Borehole Diameter	BX (60mm (2.36in.))

<sup>&</sup>lt;sup>1</sup>Depends on rock modulus

<sup>&</sup>lt;sup>2</sup>High temperature versions (up to 200°C) available on request



# **Appendix 2**

### MODEL VCE-4200/4210/4202 CONCRETE EMBEDMENT TYPE

These Strain Gages are designed for direct embedment in concrete. The VCE-4200 (standard model) has a I 53mm (6in.) gage length and 1 me sensitivity and is commonly used for strain measurements in foundations, piles, bridges, dams, tunnel linings, etc. It is also available as a high temperature version (up to 200°C). The VCE-4210 has the same range as the Model 4200 but has a 250mm (10in.) gage length making it particularly suitable for use in large aggregate concrete. The 4202, with a 51mm (2in.) gage length, is designed for laboratory use and/or where there are space limitations.

SPECIFICATIONS	4200	4210	4202
Standard Range	3000με	3000με	3000με
Sensitivity	1.0με	0.4με	0.4με
Accuracy	±1.0% F.S.	±1.0% F.S.	±1.0% F.S.
Nonlinearity	<0.5%	<0.5%	<0.5%
Temperature Range	-20°C to +80°C		
Active Gage Length	150mm (5.875in.)	250mm (10in.)	51mm (2in.)

