

SKB TR-14-02

Initial state report for the safety assessment SR-PSU

In the earlier distributed report, there are errors that now have been corrected. The changes are listed in the table below. An updated pdf version of the report, with the table printed on the back of the title page, can be found at www.skb.se/publications.

Updated 2015-10

Location	Original text	Corrected text
Page 42, Figure 3-4	Wrong data in figure	Figure updated with correct data
Page 50, last paragraph	...waste type package (SKB 2013b)...	...waste type package (SKB 2013b, SKBdoc 1481419 (Mo-93))...
Page 52, table head	...in the Inventory report (SKB 2013b).	...in the Inventory report (SKB 2013b, SKBdoc 1481419 (Mo-93)).
Page 52, Table 3-16	Wrong data in table	Table updated with correct data
Page 53, Table 3-17	Wrong data in table	Table updated with correct data
Page 100, Section 12.1.6, second sentence	...in the Inventory report (SKB 2013b).	...in the Inventory report (SKB 2013b, SKBdoc 1481419 (Mo-93)).
Page 121, updated reference	1427105 ver 1.0	1427105 ver 4.0
Page 121, new reference		SKBdoc 1481419 ver 1.0. Ny beräkning av Mo-93 i normkolli till PSU 2015-05 (In Swedish.) SKB, 2015

Svensk Kärnbränslehantering AB
Swedish Nuclear Fuel
and Waste Management Co
Box 250, SE-101 24 Stockholm
Tel +46 8 459 84 00

